

09 September 2020

Mr. Charles Palmer
Office of the State Engineer
5550 San Antonio Dr. NE
Albuquerque, New Mexico
Dist1.meterreadings@state.nm.us

RE: Permit RG-69659, RG-73531T

Dear Mr. Palmer:

Below is the meter report for the month of August 2020. A total of 13,399,897 gallons of water were discharged through the CW-1 treatment system to an infiltration gallery located in the Calabacillas Arroyo. A total of 2,529,412 gallons were discharged through the CW-2 treatment system to rapid infiltration pond numbers 2 and 3 located northwest of the treatment building.

Date	CW-1		CW-2	
	Meter Reading	Discharge	Meter Reading	Discharge
01/01/2020	453,440,391	0	79,788,446	0
01/31/2020	466,926,228	13,485,837	82,327,681	2,539,235
02/29/2020	479,539,761	12,613,533	84,696,707	2,369,026
03/31/2020	492,534,350	12,994,589	87,181,293	2,484,586
04/30/2020	505,497,929	12,963,579	89,587,621	2,406,328
05/31/2020	518,902,985	13,405,056	92,025,855	2,438,234
06/30/2020	531,890,331	12,987,346	94,213,672	2,187,817
07/31/2020	545,300,370	13,410,039	96,748,265	2,534,593
08/31/2020	558,700,267	13,399,897	99,277,677	2,529,412
Total (gallons)		105,259,876		19,489,231

Sincerely,

EA ENGINEERING, SCIENCE,
AND TECHNOLOGY, INC., PBC



Bob Marley
Project Manager